



BEARING & POWER TRANSMISSION SOLUTIONS

# Case Study

## Quick-Flex Coupling



### INDUSTRY

Packaging – Cardboard Box Plant

### PROBLEM

The Original Equipment coupling was failing every 8 weeks, causing unscheduled down time and costly production losses.



### APPLICATION

Emba 170 Prefeeder - Cardboard in Feed Conveyor

### SOLUTION

BSC redesigned the OE coupling to a Quick-Flex Coupling. The life of the coupling has increased significantly and has now reached 12 months without failure.

### BENEFIT

The customer signed off a \$63,600 costdown after 6 months. This value has since doubled by reaching 12 months without failure.



Sustainability Solutions