



BEARING & POWER TRANSMISSION SOLUTIONS

Case Study

Blue Brute Bearings



INDUSTRY

Poultry Processing Plant

APPLICATION

Ezy Loader - Front Dock

PROBLEM

The cast iron pillow block units were breaking on average twice per month causing unscheduled and costly downtime during production.

SOLUTION

BSC were asked to assist and redesigned the application to suit the Blue Brute Bearings. These units are still in operation after 19 months.

BENEFIT

Cost Down signed off for \$384,000 after 16 months continuous operation without failure.



Sustainability Solutions